Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
<u> 1</u>	398	235/462.25.ccls.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/09/05 17:51
L5	969	235/472.01.ccls.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/09/05 17:52
L6	3019	switch\$4 same (state or status) same resonant	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/09/05 17:52
L7	0	L6 and 5	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/09/05 17:53
L8	846	310/68b:ccls.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/09/05 17:53
L9	1415	310/68r.ccls.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/09/05 17:53
L10	0	310/459.ccls.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/09/05 17:53
L11	197	318/459.ccls.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/09/05 18:03
L12	91	318/500.ccls.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/09/05 18:07
L13	669	318/727.ccls.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/09/05 18:07
L14	3770	feedback same resonator	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/09/05 18:07
L15	2	5 and 14	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/09/05 18:08
L16	0	8 and 14	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/09/05 18:08
L17	0	9 and 14	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/09/05 18:08
L18	0	13 and 14	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/09/05 18:08

L19	5	(8 or 9 or 13) and resonator	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/09/05 18:12
L20	3	1 and resonator	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/09/05 18:09
L21	15	(8 or 9 or 13) and resonat\$4	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/09/05 18:11
L22	4	1 and resonat\$4	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/09/05 18:11
L23	451	(8 or 9 or 13) or 1 or 5 or 11	US-PGPUB	OR	ON	2005/09/05 18:13
L24	28	23 and feedback.clm.	US-PGPUB	OR	ON	2005/09/05 18:13
S1	65	resonant adj motor	US-PGPUB; USPAT; EPO; JPO	OR	ON .	2005/04/21 13:55
S2	38	oscillat\$4 same motor same (feedback feed adj back) same coil same switch\$3	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/09/05 17:37
S3	19061	(first adj (wind\$4 coil)) same (second adj (wind\$4 coil))	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/04/21 07:59
S4	295	S3 same (feedback feed adj back)	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/04/21 07:59
S5	52	S4 same switch	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/04/21 08:05
S6	1	S5 and "235"/\$7.ccls.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/04/21 08:00
S7	376	235/462.25.ccls.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/04/21 08:05
S8	2	S1 and S7	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/04/21 08:05
S9	17	("5280163").URPN.	USPAT	OR	ON	2005/04/21 08:08
S10	11	("3816709" "3952217" "4044283" "4387297" "4502752" "4930848" "4992717" "5003164" "5009473" "5019764" "5126545").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/04/21 08:11
S11	17	("4992717").URPN.	USPAT	OR	ON	2005/04/21 08:13

S12	16	("4251798" "4341982" "4387297" "4496831" "4575625" "4593186" "4661826" "4709195" "4829217" "4871904" "4967135" "4992717" "5003164" "5010242" "5013899" "5019764").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/04/21 08:16
S13	13	(winding\$1 adj40 winding\$1) same (drive near2 signal) same switch same amplifier same feedback\$1	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/04/21 14:09
S14	54	(winding\$1 adj40 winding\$1) same (drive near2 signal) same switch same amplifier same feedback\$1	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/04/21 13:59
S15	4051	resonan\$4 near10 motor\$1	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/04/21 14:03
S16	4	S15 same bemf	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/04/21 14:04
S17	1248	318/459,500,661,727.ccls.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/04/21 14:04
S18	2127	310/68r,68b.ccls.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/04/21 14:04
S19	8	S17 and S18	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/04/21 14:06
S20	1248	Irc	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/04/21 14:06
S21	0	S20 same S15	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/04/21 14:07
S22	2	S20 and S15	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/04/21 14:07
S23	466068	motor same drive same\$4 same signal\$4 same feedback\$1	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/04/21 14:09
S24	414723	motor same drive same\$4 same signal\$4 same feedback\$1	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/04/21 14:09

S25	7	(winding\$1 adj40 winding\$1) same (drive near2 signal) same switch same amplifier same feedback\$1	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/04/22 08:48
S26	0	motor same srive\$4 same signal\$4 same feedback\$1	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/04/21 14:10
S27	9985	motor same drive\$4 same signal\$4 same feedback\$1	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/04/21 14:10
S28	1070	motor same drive\$4 same signal\$4 same feedback\$1 same (state or status)	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/04/21 14:10
S29	. 5	S28 same resonant	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/04/21 14:12
S30	2899	switch\$4 same (state or status) same resonant	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/04/21 14:13
S31	1103	S30 same signal\$1	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/04/21 14:12
S32	112265	switch\$4 same (state or status) same control\$4 same signal\$1	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/04/21 14:13
S33	1335	S32 and S27	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/04/21 14:14
S34	50	(resonant near20 motor) same drive\$4 same signal\$4 same feedback\$1	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/04/21 14:14
S35	14	(coil\$1 adj40 coil\$1) same drive same signal same switch same amplifier same feedback\$1 same control	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/04/21 14:23
S36	30	(coil\$1 adj40 coil\$1) same drive same signal same switch same amplifier same feedback\$1	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/04/21 14:23
S37	16	S36 not S35	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/04/21 14:27
S39	0	(winding\$1 adj40 winding\$1) same drive same circuit\$4 same switch\$4 same anplifier same feedback\$1	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/04/21 14:28
S40	0	(winding\$1 adj40 winding\$1) same drive same switch\$4 same anplifier same feedback\$1	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/04/21 14:28

S41	6	(resonant near20 motor) same switch same feedback	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/04/21 14:36
S42	2	("5949177"):URPN.	USPAT	OR	ON	2005/04/22 08:33
S43	21	mylar adj motor	USPAT	OR	ON	2005/04/22 08:33
S44	1	("4709195"):PN.	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/04/22 08:39
S45	13	("4983869" "4983870" "5003211" "5250865" "5264982" "5313399" "5315197" "5491396" "5686772" "5760510" "5760511" "5844339" "6121704").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/04/22 08:40
S46	3	("6259179").URPN.	USPAT	OR	ON	2005/04/22 08:47
S47	. 16	(winding\$1) same (drive near2 signal) same switch same amplifier same feedback\$1	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/04/22 08:57
S48	17196	switch\$1 near20 (feedback)	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/04/22 08:57
S49	1	S48 same resonant adj motor	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/04/22 08:58
S50	217	S48 same resonant	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/04/22 08:58
S51	59	S50 same (coil\$1 winding\$1)	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/04/22 09:05
S52	1483	feedback adj winding	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/04/22 09:06
S53	327	S52 same switch	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/04/22 13:47
S54	35	S53 same amplifier	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/04/22 09:06
S55	1483	feedback adj winding	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/04/22 13:47
S56	126	S55 near20 switch	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/04/22 13:49

S57	12	S56 same amplifier	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/04/23 10:18
S58	4	(("5003164") or ("5126545") or ("5280163") or ("5736797")).PN.	US-PGPUB; USPAT; EPO; JPO	OR	OFF	2005/04/23 10:21
S59	11	"657690"	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/04/23 10:22
S60	60591	(control adj4 signal) same (switch\$4 adj4 signal)	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/04/23 10:22
S61	674	S60 same (winding\$1 near40 winding\$1)	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/04/23 10:22
S62	55	S61 same feedback	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/04/23 10:40
S63	6	S61 same (feedback near20 loop)	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/04/23 10:40
S64	14	("4688158").URPN.	USPAT	OR	ON	2005/04/23 10:50
S65	0	(resonant adj motor) near20 transformer	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/04/25 08:50
S66	2	(resonant adj motor) same transformer	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/04/25 08:52
S67	33	(resonant same rotor) same transformer	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/04/25 08:52